

Inspection Photos

March 29, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335216

Location Name: SAVAGE-66S94W/33SENW

Inspection Document #: 702801414

Garfield County, CO

SENW Section 33 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SAVAGE-66S94W/33SENW
Location ID: 335216



Photo 1. Photo taken from the entrance shows an overview of the location.



Inspection Photos
Location Name: SAVAGE-66S94W/33SENW
Location ID: 335216




Photo 2. Photos show production areas.

Inspection Photos

Location Name: SAVAGE-66S94W/33SENW

Location ID: 335216



Photo 3. Photos show two (2) unmarked anchors within the tank battery berm (left) and in the western interim area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801414

Inspection Photos
Location Name: SAVAGE-66S94W/33SEW
Location ID: 335216



Photo 4. Photos show western (left) and eastern (right) interim areas.

Inspection Photos

Location Name: SAVAGE-66S94W/33SEW

Location ID: 335216



Photo 5. Photos show an example of rill erosion on the fill slope to the east of the location (left) continuing offsite into reference areas in the form of rill erosion and sediment deposition (right).

Inspection Photos
Location Name: SAVAGE-66S94W/33SEW
Location ID: 335216



Photo 6. Photo shows an example of erosion on the fill slope to the east of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801414