

# Inspection Photos

March 29, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 324027

Location Name: SAVAGE-66S94W/33SWNE

Inspection Document #: 702801418

Garfield County, CO

SWNE Section 33 T6S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: SAVAGE-66S94W/33SWNE  
Location ID: 324027



**Photo 1.** Photo taken from the entrance shows an overview of the location.



Inspection Photos  
Location Name: SAVAGE-66S94W/33SWNE  
Location ID: 324027





Photo 2. Photos show production areas.

Inspection Photos  
Location Name: SAVAGE-66S94W/33SWNE  
Location ID: 324027



**Photo 3.** Photo shows a bull plug/cap is not installed on a load line.

Inspection Photos  
Location Name: SAVAGE-66S94W/33SWNE  
Location ID: 324027



**Photo 4.** Photos show northern (left) and southern (right) interim areas.