

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RW 3-27 Pad

Location ID: 323812



Photo # 4101 From entrance to location



Photo # 4102 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RW 3-27 Pad

Location ID: 323812



Photo # 4103 Meter calibration info not conspicuously posted