

# Inspection Photos

API: 043-40014

Operator: JAVERNICK OIL

Inspection Date: 3/31/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 043-40014 | Date: 3/31/2023

## Inspection Photos



**Photo 1.** Facing northeast along the access road. The road has not been recontoured and reclaimed. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40014 | Date: 3/31/2023



## Inspection Photos



**Photo 2.** Facing northeast along the access road. The road has not been recontoured and reclaimed. The soils are bare of vegetation and susceptible to erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40014 | Date: 3/31/2023



## Inspection Photos



**Photo 3.** Facing northeast toward the location (yellow arrow). There is another access road (red arrow) that leads north to the Drapper4 well site which has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40014 | Date: 3/31/2023



## Inspection Photos



**Photo 4.** Facing northeast at the abandoned wellsite which has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40014 | Date: 3/31/2023



## Inspection Photos



**Photo 5.** Facing north along the access road between the Hassler 24 and Drapper4 well site. This area has not been recontoured and reclaimed and is susceptible to further erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40014 | Date: 3/31/2023



## Inspection Photos



**Photo 6.** Facing southwest along the access road between the Hassler 24 and Drapper 4 well site. This area has not been recontoured and reclaimed and is susceptible to further erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40014 | Date: 3/31/2023



## Inspection Photos



**Photo 7.** Facing southwest toward the surrounding undisturbed vegetation cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40014 | Date: 3/31/2023