

Inspection Photos
Location Name: Gray 1 Hepp Battery
GPS: 40.276021 -104.914322



Photo 1 Well head



Photo 2 TNK BTRY

Inspection Photos
Location Name: Gray 1 Hepp Battery
GPS: 40.276021 -104.914322



Photo 3 roads deep ruts and swabbing unit laid down.



Photo 4 TNK BTRY tank not painted.



Inspection Photos
Location Name: Gray 1 Hepp Battery
GPS: 40.276021 -104.914322



Photo 5 unused equipment pipe and parts on ground



Photo 6 Trash on production tank and in containment.

Inspection Photos
Location Name: Gray 1 Hepp Battery
GPS: 40.276021 -104.914322



Photo 7 production equipment



Photo 8 production equipment

Inspection Photos
Location Name: Gray 1 Hepp Battery
GPS: 40.276021 -104.914322



Photo 9 Meter station 235486 showing production



Photo 10 Meter station 235486 showing production

Inspection Photos
Location Name: Gray 1 Hepp Battery
GPS: 40.276021 -104.914322




Photo 11 Well written on door of meter house



Photo 12 meter house not in operation used for storage.

Inspection Photos
Location Name: Gray 1 Hepp Battery
GPS: 40.276021 -104.914322



Photo 13 Roads deep ruts and holding water.