

**Inspection Photos**  
**Location Name: Camenisch Facility (2)**  
**Location ID:**



**Photo 1 Stained soil 2" line on crude oil tank.**