

Inspection Photos
Location Name: GREENLAUGH, NAUMAN 1-23
Location ID: 320150



Photo# 1 Crude Tank and P/W Tank.



Photo# 2 No Bullplug.

Inspection Photos
Location Name: GREENLAUGH, NAUMAN 1-23
Location ID: 320150



Photo# 3 No Bullplug.




Photo# 4 No Bullplug.



Inspection Photos
Location Name: GREENLAUGH, NAUMAN 1-23
Location ID: 320150




Photo# 5 Separator & ECDs.



Photo# 6 No Bullplug & plastic bucket full of crude in separator cabinet.



Inspection Photos
Location Name: GREENLAUGH, NAUMAN 1-23
Location ID: 320150



Photo# 7 Stained soil in separator cabinet.



Photo# 8 Pump jack.