

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HENRY-67S95W /3SWNW.

Location ID: 334731



Photo #9474 From entrance to location.



Photo #9487 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HENRY-67S95W /3SWNW.

Location ID: 334731



Photo #9488 From entrance to location.



Photo #9492 Undesirable Plant Species

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HENRY-67S95W /3SWNW.

Location ID: 334731



**Photo #9491 Undesirable Plant Species**



**Photo #9479 Bird protector insufficient.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HENRY-67S95W /3SWNW.

Location ID: 334731



Photo #9495 Unused equipment.



Photo #9494 Unused equipment and undesirable plant species.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HENRY-67S95W /3SWNW.

Location ID: 334731



Photo #9493 Loadline open ended.



Photo #9487 Calibration cards not conspicuously posted.