

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



Photo # 4128 From entrance to location



Photo # 4129 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



Photo # 4132 Location



Photo # 4133 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



Photo # 4134 Location



Photo # 4138 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 Pad

Location ID: 324057



Photo # 4139 Containment capacity inadequate/Failure to maintain containment