

# LARAMIE ENERGY LLC, CC/0697-16D Pad

Location # 335203



Wellheads – Photo #01835



Separator – Photo #01839

# LARAMIE ENERGY LLC, CC/0697-16D Pad

Location # 335203



**Tank Battery – Photo #01844**

**Inadequate Berm Capacity – Photo #01846**

# LARAMIE ENERGY LLC, CC/0697-16D Pad

Location # 335203



**Lease Road: Degradation/Sediment Transport –  
Photo #01831**



**Lease Road: Cut Slope Erosion/Sediment Migration  
– Photo #01832**

# LARAMIE ENERGY LLC, CC/0697-16D Pad

Location # 335203



**Site: Degradation/Sediment Transport – Photo #01843**



**Site: Cut Slope Erosion/Run-On to Location – Photo #01838**

# LARAMIE ENERGY LLC, CC/0697-16D Pad

Location # 335203



**Site Degradation/Sediment Transport – Photo #01842**



**Lease Road: Failed BMP/Slope Erosion/Sediment Migration – Photo #01850**