

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 208-20 Pad

Location ID: 324044



Photo # 4109 From entrance to location



Photo # 4110 From entrance to location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 208-20 Pad

Location ID: 324044



Photo # 4111 Location



Photo # 4112 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 208-20 Pad

Location ID: 324044



Photo # 4113 Location



Photo # 4114 Meter calibration info not conspicuously posted

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 208-20 Pad

Location ID: 324044



Photo # 4115 Meter calibration info not conspicuously posted



Photo # 4117 Tank label info incorrect