

# Inspection Photos

API: 071-09369

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/4/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09369 | Date: 4/4/2023

## Inspection Photos



**Photo 1.** Facing southwest along the main road to the location. There are areas of vehicle rutting that will need to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09369 | Date: 4/4/2023

## Inspection Photos



**Photo 2.** Facing east toward the location. There was a recent frac operation at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09369 | Date: 4/4/2023



## Inspection Photos



**Photo 3.** There is numerous areas of oil stained soil from the equipment parked on location which will need to be cleaned up. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09369 | Date: 4/4/2023

## Inspection Photos



**Photo 4.** There is oily fluid sprayed out at the onto the ground at the wellhead that has not been cleaned up. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09369 | Date: 4/4/2023



## Inspection Photos



**Photo 5.** There is oily fluid the engine skid and spilled out onto the ground that needs to be cleaned up.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09369 | Date: 4/4/2023

## Inspection Photos



**Photo 6.** The pit liner degraded. A red sign has been put up “Don Not use”. The fence around the pit has been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09369 | Date: 4/4/2023



## Inspection Photos



**Photo 7.** There is white frac sand that has now blown further across the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09369 | Date: 4/4/2023



## Inspection Photos



**Photo 8.** There is frac sand spilled out over the ground that was not properly handled and has now blown further across the location and offsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09369 | Date: 4/4/2023



## Inspection Photos



**Photo 9.** There is white frac sand that has blown off the south side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

API: 071-09369 | Date: 4/4/2023



## Inspection Photos



**Photo 10.** Facing northeast at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09369 | Date: 4/4/2023