



99999999

## SITE INSPECTION FORM

12105669 *PROD*

LOCATION SWNW 8-35-55W  
OPERATOR DAWSON OIL CORP  
WELL NAME #1 JOLLY 358

FIELD RAMP  
COUNTY WASHINGTON  
PERMIT # \_\_\_\_\_

## DATE OF INSPECTION DURING DRILLING: \_\_\_\_\_

RIG \_\_\_\_\_ SURFACE CASING: \_\_\_\_\_ DEPTH: \_\_\_\_\_  
BOP'S \_\_\_\_\_ RETURNS: \_\_\_\_\_ WOC: \_\_\_\_\_  
CONTACT \_\_\_\_\_ CMT VOL: \_\_\_\_\_  
ADEQUATE AQUIFER PROTECTION? \_\_\_\_\_  
COMMENTS \_\_\_\_\_

## DATE OF INSPECTION AFTER COMPLETION: \_\_\_\_\_

FRACED: YES \_\_\_\_\_ NO \_\_\_\_\_ PRODUCTION STRING: \_\_\_\_\_  
WATER DISPOSAL: PITS \_\_\_\_\_, INJECTED \_\_\_\_\_, COMMERCIAL \_\_\_\_\_, UNKNOWN \_\_\_\_\_, N.A. \_\_\_\_\_  
PITS: PERMIT Y \_\_\_\_\_ N \_\_\_\_\_, SKIM TANK Y \_\_\_\_\_ N \_\_\_\_\_, DIMENSIONS \_\_\_\_\_  
LEASE SIGN: YES \_\_\_\_\_ NO \_\_\_\_\_ TANK ID: YES \_\_\_\_\_ NO \_\_\_\_\_ NA \_\_\_\_\_ FENCED: YES \_\_\_\_\_ NO \_\_\_\_\_  
SURFACE EQUIPMENT: \_\_\_\_\_  
COMMENTS: \_\_\_\_\_

DATE OF P&A INSPECTION 8/22/86

PITS BACKFILLED: YES ☒ NO \_\_\_\_\_ SURFACE RECLAIMED: YES ☒ NO \_\_\_\_\_  
HOLE MARKER: YES \_\_\_\_\_ NO \_\_\_\_\_ SITE CLEAN: YES ☒ NO \_\_\_\_\_  
BOND RELEASE OK: YES ☒ NO \_\_\_\_\_ LANDOWNER RELEASE: YES \_\_\_\_\_ NO \_\_\_\_\_  
COMMENTS: SITE IS WELL GRATED PASTURE - NO SIGN OF WELL.

## DATE OF SAFETY INSPECTION \_\_\_\_\_

COMMENTS: \_\_\_\_\_



00400385

INSPECTOR R. VACLAVIKAPI No. 05-121-5669P&A Inspected: Yes ☒ No \_\_\_\_\_*efb*