

RCL



LOCATION SWSE 8, 35, 55W FIELD WC
 OPERATOR Transcontinent COUNTY Washington
 WELL NAME Jolly 1-8 FORMATION _____

DATE OF INSPECTION DURING DRILLING: _____

RIG _____ SURFACE CASING: _____
 BOP'S _____ DEPTH _____ WOC _____
 CONTACT _____ CMT VOL _____ RETURNS _____
 ADEQUATE AQUIFER PROTECTION? _____
 COMMENTS _____

DATE OF INSPECTION AFTER COMPLETION: _____

FRACED: _____ PRODUCTION STRING: _____
 CBL CHECKED? _____ DEPTH _____ STAGED _____
 WATER DISPOSAL METHOD _____
 PITS: PERMIT _____ TDS _____ SKIM TANK _____
 DIMENSION: _____ SCREEN: _____ LINER: _____

 LEASE SIGN: _____ TANK ID: _____ FENCED? _____
 SURFACE EQUIPMENT: _____

DATE OF FINAL P&A INSPECTION 2/25/86

PLUG 1 10 SX @ 130 SURFACE RECLAIMED? No
 PLUG 2 20 SX @ surface SITE CLEAN? Yes
 PLUG 3 _____ SX @ _____ LANDOWNER RELEASE? _____

INSPECTOR SP

P&A 11-11-85

*Pits still open, cas. not visible
 Spoke w/ Mrs. Jolly - weather has
 been bad + Co. will fill pits when
 weather permits.*