

Inspection Photos

Location Name: Dillard USX/AB29-02

Location #: 420817



Photo #1

Dillard USX AB29-02 (123-32720) Wellsite

Temporarily Abandoned | TA

CA: Wellhead sign NOT posted.

CA: Weed encroachment at wellsite.



Photo #2

Dillard - USX AB 29-17, 29-02, 29-7 Battery site

Abandoned: ALL Equipment Removed

prior insp. photo



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources