

Inspection Photos
Location Name: Ball Ranch/GW27-63HN
Location #: 427641



Photo #1

Ball Ranch GW27-63HN (123-35058) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 25 yds.



Photo #2

Ball Ranch GW27-63HN Battery site
Abandoned: Most Equipment Removed
CA: Unnecessary Equipment
Gas meter runs, blowdown header

Inspection Photos
Location Name: Ball Ranch/GW27-63HN
Location #: 427641



Photo #3

Ball Ranch GW27-63HN Battery site

Abandoned: Most Equipment Removed

CA: Unnecessary Equipment

Gas meter runs, blowdown header