

Inspection Photos
Location Name: YC-4
API #: 083-06584



11/2/22 inspection photo



4/3/23 photo

Inspection Photos
Location Name: YC-4
API #: 083-06584



11/2/22 photo



4/3/23 photo

Inspection Photos
Location Name: YC-4
API #: 083-06584



Shovel test showing loose materials



Roadbase loose, not compacted or stabilized, may become new source material in next storm event if no further action taken.

Inspection Photos
Location Name: YC-4
API #: 083-06584



**Ditch areas partially filled in with loose new material, no
check dams or other BMPs on step section**