

Inspection Photos
Location Name: Shoe #1
Location ID: 317489



Photo 1 WH sign.

Photo 2 WH

Inspection Photos
Location Name: Shoe #1
Location ID: 317489



Photo 3 TB sign.

Photo 4 TB no labels and placards .

Inspection Photos
Location Name: Shoe #1
Location ID: 317489



Photo 5 Horizontal Heated Separator.

Photo 6 Gas Meter Run.