

Interim Reclamation and Stormwater Inspection

Date: 03/31/2023

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 432694

Inspection Document #: 708200079

Weld County, CO

NENE Section 35 T9N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photo 1. It appears the Operator has performed the corrective action and installed wildlife exclusion device at the entrance of the compressor shed.

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photo 2. Close-up photo of residual antifreeze observed within containment of engine skid. Based on Operator submitted FIRR, the Operator cleaned up the free antifreeze and placed rags within the containment to soak up any remaining fluids to perform the corrective action. At the time of this inspection, some residual fluid was discovered and appears to be diluted. The Operator is being required to inspect the equipment and remove any remaining fluid to prevent further occurrences.

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photo 3. See comments in Photo 2.

Inspection Photos
Location Name: Shull 1-35-9-60 Pad
Location ID: 432694



Photo 4. Facing east at raised tank and secondary containment. During this inspection, Staff observed a milky /unknown fluid within the secondary containment that will need to be properly disposed of.