

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS RWF 41-30 Pad

Location ID: 335141



Photo # 4283 From entrance to location



Photo # 4286 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS RWF 41-30 Pad

Location ID: 335141



Photo # 4284 Location



Photo # 4285 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS RWF 41-30 Pad

Location ID: 335141



Photo # 4287 Location



Photo # 4293 Meter calibration info not conspicuously posted

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS RWF 41-30 Pad

Location ID: 335141



Photo # 4294 Meter calibration info not conspicuously posted



Photo # 4301 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS RWF 41-30 Pad

Location ID: 335141



Photo # 4320 Debris



Photo # 4321 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS RWF 41-30 Pad

Location ID: 335141



**Photo # 4310 Lack of stabilization/insufficient tracking  
BMP's**



**Photo # 4312 Lack of stabilization/insufficient tracking  
BMP's**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS RWF 41-30 Pad

Location ID: 335141



**Photo # 4313 Lack of stabilization/insufficient tracking  
BMP's**