

**Chevron U.S.A. Inc.
A.C. McLaughlin 71X
Location #315321**



Access road and entrance to location



Diversion ditch full of sediment and erosion onto location

**Chevron U.S.A. Inc.
A.C. McLaughlin 71X
Location #315321**



Diversion ditch full of sediment and erosion onto location

Sediment movement during snow removal

**Chevron U.S.A. Inc.
A.C. McLaughlin 71X
Location #315321**



Wellhead view looking West



Wellhead sign

**Chevron U.S.A. Inc.
A.C. McLaughlin 71X
Location #315321**



Sediment migration on to location



Sediment migration and erosion on location