

# CAERUS PICEANCE LLC, PUCKETT-66S96W/31NESW

Location # 335092



Wellheads – Photo #01851




Separators – Photo #01853

# CAERUS PICEANCE LLC, PUCKETT-66S96W/31NESW

Location # 335092



Tank Battery – Photo #01861



Chemical Tank – Photo #01852

# CAERUS PICEANCE LLC, PUCKETT-66S96W/31NESW

Location # 335092



**Lack of Stabilization/Inadequate Tracking BMP –  
Photo #01866**



**Transport of Sediment – Photo #01868**