

CAERUS PICEANCE LLC, PUCKETT-66S96W/31NESW

Location # 335093



Wellheads – Photo #01857



Separator – Photo #01858

CAERUS PICEANCE LLC, PUCKETT-66S96W/31NESW

Location # 335093



Tank Battery/Chemical Tank – Photo #01861



Unused Equipment – Photo #01862

CAERUS PICEANCE LLC, PUCKETT-66S96W/31NESW

Location # 335093



Open-Ended Line – Photo #01863

Open-Ended Line – Photo #01864

CAERUS PICEANCE LLC, PUCKETT-66S96W/31NESW

Location # 335093



Unused Equipment (Ladder) – Photo #01865



Lack of Stabilization/Inadequate Tracking BMP – Photo #01866

CAERUS PICEANCE LLC, PUCKETT-66S96W/31NESW

Location # 335093



Apr 4, 2023 at 11:13:48
Parachute CO 81635
United States



Apr 4, 2023 at 11:13:52
Parachute CO 81635
United States

Degradation/Sediment Transport – Photo #01867

Degradation/Sediment Transport – Photo #01868