

CAERUS PICEANCE LLC, PUCKETT-66S96W/31SESW

Location # 335383



Wellheads/Lack of Stabilization – Photo #01870



Separators – Photo #01872

CAERUS PICEANCE LLC, PUCKETT-66S96W/31SESW

Location # 335383



Tank Battery – Photo #01874

Methanol Tank – Photo #01873

CAERUS PICEANCE LLC, PUCKETT-66S96W/31SESW

Location # 335383



Chemical Tank – Photo #01876



Gas Meter – Photo #01880

CAERUS PICEANCE LLC, PUCKETT-66S96W/31SESW

Location # 335383



Cut Slope Erosion/Run-On – Photo #01877



Cut Slope Erosion/Run-On – Photo #01878