

# Interim and Stormwater Inspection

April 3, 2023

Operator: Kerr McGee Oil & Gas # 47120

Location ID: 306014

Inspection Document #:709400124

Weld County

SWNW, Section 1, 1N66W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: AMATO 1N66W  
Location ID: 306073



Photo 1. Photo taken of location sign





Inspection Photos  
Location Name: AMATO 1N66W  
Location ID: 306073



**Photo 2.** Photo taken of weeds accumulated around production tanks.



**Photo 3.** Photo of weeds accumulated on fence and in site corner.



Inspection Photos  
Location Name: AMATO 1N66W  
Location ID: 306073



**Photo 4. Photo taken of weeds accumulated around and under equipment.**



**Photo 5. See Photo 4 comments**