

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403367204

Date Received:

04/06/2023

Spill report taken by:

Anderson, Laurel

Spill/Release Point ID:

483544

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

OPERATOR INFORMATION

Name of Operator: <u>HIGHPOINT OPERATING CORPORATION</u>	Operator No: <u>10071</u>	Phone Numbers
Address: <u>555 17TH ST STE 3700</u>		Phone: <u>(303) 2947864</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Jacob Evans</u>		Mobile: <u>(303) 8293811</u>
		Email: <u>jevans@civiresources.com</u>

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 403271218

Initial Report Date: 12/25/2022 Date of Discovery: 12/25/2022 Spill Type: Recent Spill

Spill/Release Point Location:

QTRQTR SESE SEC 19 TWP 12N RNG 62W MERIDIAN 6Latitude: 40.989298 Longitude: -104.354732Municipality (if within municipal boundaries): _____ County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

Reference Location:

Facility Type: TANK BATTERY☒ Facility/Location ID No 418462Spill/Release Point Name: Randall Creek 6-19☐ Well API No. (Only if the reference facility is well) 05- -☐ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): >=5 and <100Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use: OTHEROther(Specify): Range LandWeather Condition: Clear 30'sSurface Owner: FEE

Other(Specify): _____

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A compromised produced water load line released approximately 50 bbls of produced water to the pad surface. The release was completely contained to the pad surface. Vac trucks are en route to begin removing the remaining fluid. Upon clearance of utility locates, the impacted soil will be removed and confirmation soil samples will be submitted for laboratory analysis in compliance with COGCC Table 915-1.

List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
12/25/2022	CPW	Brandon Marette	-on file	Notified of release
12/25/2022	Surface Owner	on file	-on file	Notified of release
12/25/2022	Weld Co. OEM	Dave Burns	-on file	Notified via OEM report

REPORT CRITERIA

Rule 912.b.(1) Report to the Director (select all criteria that apply):

- No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.
- Waters of the State: _____ Public Water System: _____
- Residence or Occupied Structure: _____ Livestock: _____
- Wildlife: _____ Publicly-Maintained Road: _____
- Yes Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.
- Yes Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.
- No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak
- Enter the approximate time of discovery _____ (HH:MM)
- Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 _____
- Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? _____
- Enter the Document Number of the Initial Accident Report, Form 22 _____
- Was there damage during excavation? _____
- Was CO 811 notified prior to excavation? _____
- Yes Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.
- Estimated Volume of Impacted Solids (cu. yd.): _____ 30
- No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:
- ☐ The presence of free product or hydrocarbon sheen Surface Water
- ☐ The presence of free product or hydrocarbon sheen on Groundwater
- ☐ The presence of contaminated soil in contact with Groundwater
- ☐ The presence of contaminated soil in contact with Surface water

No	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylights from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.
	<input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 12/27/2022		
----	--------------------------------------	--	--

FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	50	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: _____

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) ☒ Soil ☐ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): _____ Width of Impact (feet): _____

Depth of Impact (feet BGS): _____ Depth of Impact (inches BGS): _____

How was extent determined?

The extent of impacts will be determined through excavation of impacted soil. Confirmation soil samples will be collected for laboratory analysis of Table 915-1 organics, metals, TPH C6-36, SAR, EC, pH, and boron. Per DWR water well permit# 109484, the static water level is 60' below ground surface Highpoint proposes to utilize Table 915-1 residential soil screening levels for this spill.

Soil/Geology Description:

road base

Depth to Groundwater (feet BGS)	60	Number Water Wells within 1/2 mile radius:	0
---------------------------------	----	--	---

If less than 1 mile, distance in feet to nearest	Water Well	4149	None <input type="checkbox"/>	Surface Water	2090	None <input type="checkbox"/>
	Wetlands		None <input checked="" type="checkbox"/>	Springs		None <input checked="" type="checkbox"/>
	Livestock		None <input checked="" type="checkbox"/>	Occupied Building		None <input checked="" type="checkbox"/>

Additional Spill Details Not Provided Above:

The produced water soaked into the ground surface. Excavation of impacted material will be scheduled. Located within a designated Pronghorn Winter Concentration HPH and a designated basin.

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 04/06/2023

Root Cause of Spill/Release Equipment Failure

Other (specify)

Type of Equipment at Point of Spill/Release: Other

If "Other" selected above, specify or describe here:

Produced water load line

Describe Incident & Root Cause (include specific equipment and point of failure)

A compromised produced water load line released approximately 50 bbls of produced water to the pad surface. The release was completely contained to the pad surface.

Describe measures taken to prevent the problem(s) from reoccurring:

Routine AVO inspections occur at all oil and gas facilities.

Volume of Soil Excavated (cubic yards): 0

Disposition of Excavated Soil (attach documentation) ☐ Offsite Disposal ☐ Onsite Treatment ☐ Other (specify)

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

- Basis for Closure:
- ☐ Corrective Actions Completed (documentation attached, check all that apply)
 - ☐ Horizontal and Vertical extents of impacts have been delineated.
 - ☐ Documentation of compliance with Table 915-1 is attached.
 - ☐ All E&P Waste has been properly treated or disposed.
 - ☒ Work proceeding under an approved Form 27 (Rule 912.c).
- Form 27 Remediation Project No: 28536
- ☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

OPERATOR COMMENTS:

Topo map, aerial image, and photos are included under the data package attachment. HighPoint is requesting closure due to work proceeding under an approved Form 27 (REM # 28536)

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Costin McQueen

Title: Senior Env Specialist Date: 04/06/2023 Email: cmcqueen@civiresources.com

COA Type	Description
0 COA	

Attachment List

Att Doc Num

Name

403367244

OTHER

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)