

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 4217 From entrance to location

Photo # 4218 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Apr 4, 2023 at 10:37:45 AM
CO



Apr 4, 2023 at 10:38:27 AM
CO

Photo # 4219 From entrance to location

Photo # 4220 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 4221 Location



Photo # 4222 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 4223 Location



Photo # 4224 Meter calibration info not conspicuously posted

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad
Location ID: 322444



Apr 4, 2023 at 10:40:33 AM
CO



Apr 4, 2023 at 10:40:46 AM
CO

Photo # 4225 Meter calibration info not conspicuously posted

Photo # 4226 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 4227 Unused Equipment




Photo # 4222 Wellhead sign missing required information

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 4230 Tank label has incorrect information