

Inspection Photos

4/05/2023

Operator: CAERUS PICEANCE LLC #10456

Location #423081

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #423081



Photo 1: Tank battery signage has been installed.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #423081



Photo 2: Repair work to liner inadequate- patch is peeling off.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #423081



Photo 3: Exposed separator lines.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #423081



Photo 4: Storage of unused equipment.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #423081



Photo 5: Tracking BMPs showing signs of disrepair.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #423081



April 5, 2023



April 5, 2023

Photo 6: Photos show sediment transport from access road onto public roadway has continued.