

# Inspection Photos

4/05/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location #440705

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #440705



**Photo 1:** Photos 1-2 taken from the current productions areas on the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west. Photos also show areas not reasonable needed for production remain. Areas of the working pad continue to lack stabilization.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #440705



**Photo 2:** See comments under photo 1.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #440705



**Photo 3:** Photos taken from the wells. Unable to find evidence that stormwater BMPs to allow for proper stormwater discharge from the Location and/or BMPs to prevent potential pollution impacts due to contact with production equipment, has been installed or maintained; stormwater appears to have continued to fill cellars at the wells.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #440705



**Photo 4:** Photos 4-5 taken from the north end of the Location. Photos show Location has not been constructed with a properly engineered outlet; stormwater runoff from the current working pad has resulted in erosion degradation to the interim areas of the Location.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #440705



**Photo 5:** See comments under photo 4. Photos also show sediment deposition/degradation due to stormwater runoff from the working pad.