

Inspection Photos

4/05/2023

Operator: CAERUS PICEANCE LLC #10456

Location #335047

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335047



April 5, 2023



April 5, 2023

Photo 1: Location overview

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335047



Photo 2: Chemical container lacks required marking/labeling/signage.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335047



Photo 3: Example of Interim areas of the Location