

Interim Reclamation and Stormwater Inspection

Date: 03/31/2023

Operator: FOUNDATION ENERGY MANAGEMENT LLC
- 10112

Location ID: 310566

Inspection Document #: 708200093

Weld County, CO

NENE Section 1 T7N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Green 1-1
Location ID: 310566



Photos 1 & 2. It appears the Operator has addressed the stormwater corrective action by installing straw wattles and backfilling rill erosion areas. However, it does not appear the BMPs were installed per good engineering practices as they were not trenched in.



Photo 3. Close up photo illustrating that the straw wattles have not been trenched in per good engineering practices.

Inspection Photos
Location Name: Green 1-1
Location ID: 310566



Photos 4 & 5. Rill erosion evident (red arrows) with no stormwater BMPs identified.

Inspection Photos
Location Name: Green 1-1
Location ID: 310566



Photo 6. Overview illustrating rill erosion and path of stormwater. This area will need additional stormwater BMPs to prevent further erosion and degradation to adjacent lands.