

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 92-29 Pad

Location ID: 324090



Photo # 4332 From entrance to location



Photo # 4333 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 92-29 Pad

Location ID: 324090



Photo # 4334 Location



Photo # 4335 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 92-29 Pad

Location ID: 324090



Photo # 4336 Debris



Photo # 4337 Debris



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 92-29 Pad

Location ID: 324090



Photo # 4341 Debris



Photo # 4343 Unused equipment



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 92-29 Pad

Location ID: 324090



**Photo # 4338 Meter calibration info not conspicuously posted**



**Photo # 4339 Meter calibration info not conspicuously posted**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 92-29 Pad

Location ID: 324090



**Photo # 4340 Meter calibration info not conspicuously posted**



**Photo # 4351 Wellhead sign illegible**