

TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location # 324177




Wellhead – Photo #01917




Separator – Photo #01919

TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location # 324177



Tank Battery – Photo #01924



Erosion/Sediment Migration onto Location – Photo #01922

TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location # 324177



Erosion/Sediment Migration – Photo #01921

Erosion/Sediment Migration – Photo #01923

TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location # 324177



**Erosion/Sediment Migration/Lack of Stabilization –
Photo #01926**