



Batch ID: 104365 Document Name: 1 File Name: 279412 - EDD1 292022.xlsx

SampleType: \_\_\_\_\_ Matrix: \_\_\_\_\_

Facility ID: 279412 Sample ID: 642299 Sample Name: Lorencito 8-1-34-67 Sample Date: 01/24/2022

Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j subsequent sample

Project Number: \_\_\_\_\_ Remediation Number: \_\_\_\_\_ Complaint Number: \_\_\_\_\_ NOAV Number: \_\_\_\_\_

Inspection Number: \_\_\_\_\_ Spill Number: \_\_\_\_\_ Laboratory: TestAmerica Inc. Lab Sample ID: 280-158028-5

**Sample Facility Attachment:**

Facility ID	Attach Num	File Name	Document Name	File Type
279412	403194975	279412 - report1 292022.pdf	Analytical Laboratory Report	PDF
279412	403194976	279412 - report2 03012022.pdf	Analytical Laboratory Report	PDF

**Sample COGCC Well Related:**

No Sample COGCC Well Related Information Provided.

**General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	04/07/2023

Total: 1 comment(s)