

Inspection Photos

API: 071-09919

Operator: DESERT EAGLE OPERATING LLC

Inspection Date: 4/6/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09919 | Date: 4/6/2023

Inspection Photos



Photo 1. Facing southeast toward the access road. Sign posted at road has been updated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 4/6/2023

Inspection Photos



Photo 2. Facing southeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 4/6/2023

Inspection Photos



Photo 3. Facing southwest at the location All disturbed soils will need to be decompacted, seeded, and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 4/6/2023

Inspection Photos



Photo 4. There is still some tree debris that remains that will need to be removed. The majority of piles of tree debris were removed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09919 | Date: 4/6/2023

Inspection Photos



Photo 5. The perimeter wattles are degraded and not functional.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 4/6/2023

Inspection Photos



Photo 6. Facing south toward the flowline trenching disturbance. The piles of tree debris were mostly removed. All disturbed soils will need to be decompacted, seeded, and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 4/6/2023

Inspection Photos



Photo 7. There is still a pile of soil and debris southwest of the wellsite that needs to be removed and soil replaced.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 4/6/2023

Inspection Photos



Photo 8. Midway at the flowline facing south.



Photo 9. Midway at the flowline facing north.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 4/6/2023

Inspection Photos



Photo 10. Facing northeast further out from the flowline. All other areas of disturbance will also need to be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 4/6/2023