

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403337499

Receive Date:

03/11/2023

Report taken by:

Steven Arauza

## Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

### OPERATOR INFORMATION

Name of Operator: <u>SUMMIT MIDSTREAM PARTNERS LLC</u>	Operator No: <u>200565</u>	<b>Phone Numbers</b>
Address: <u>910 LOUISIANA ST STE 4200</u>		Phone: <u>(832) 6086137</u>
City: <u>HOUSTON</u>	State: <u>TX</u>	Zip: <u>77002</u>
Contact Person: <u>Sherri Gregg</u>	Email: <u>sherri.gregg@summitmidstream.com</u>	Mobile: <u>(713) 2923472</u>

### PROJECT, PURPOSE & SITE INFORMATION

#### PROJECT INFORMATION

Remediation Project #: 28590 Initial Form 27 Document #: 403337499

#### PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☒ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☐ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: \_\_\_\_\_

#### SITE INFORMATION

☐ No ☐ Multiple Facilities

Facility Type: <u>SPILL OR RELEASE</u>	Facility ID: <u>480375</u>	API #: _____	County Name: <u>GARFIELD</u>
Facility Name: <u>Pig Launcher near Encana PN20 well</u>		Latitude: <u>39.418000</u>	Longitude: <u>-108.023000</u>
		** correct Lat/Long if needed: Latitude: <u>39.418008</u>	Longitude: <u>-108.022588</u>
QtrQtr: <u>SWSW</u>	Sec: <u>20</u>	Twp: <u>7S</u>	Range: <u>95W</u>
		Meridian: <u>6</u>	Sensitive Area? <input type="checkbox"/> No

#### SITE CONDITIONS

General soil type - USCS Classifications SC Most Sensitive Adjacent Land Use Non-crop land

Is domestic water well within 1/4 mile? ☐ No Is surface water within 1/4 mile? ☐ No

Is groundwater less than 20 feet below ground surface? ☐ No

## Other Potential Receptors within 1/4 mile

Ephemeral drainages are located 410' east and 325' west of the Site. The closest well with a static water level is permit 57701-F which is 3395' northwest of the Site. The static water level in that well is at a depth of 95'. Entrada contends that Residential Soil Screening Levels be applied at this Site.

## SITE INVESTIGATION PLAN

### TYPE OF WASTE:

☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste

☒ Produced Water

☐ Workover Fluids

☐ Oil

☐ Tank Bottoms

☒ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

### DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	350 sqft, 8.5 ft deep	Visual, field screening, excavation

### INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Site was excavated and sampled in August 2021. Please see attached Table, Figure, and Analytical Data.

Operator performing pigging operations in South Parachute, PN20 pad, found natural gas bubbling up through standing recent storm water at the pig launcher. Operator isolated the pad/line and blew it down. Summit investigated and contracted a vac truck to remove the standing storm water. Delineation of soil impact was still ongoing as of the initial reporting.

### PROPOSED SAMPLING PLAN

#### Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

See Additional Investigative Actions

#### Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

Groundwater was not encountered during activities at this Site.

#### Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

Summit intends to submit a 915b reclamation plan for the remainder of the exceedances at this Site with the next Form 27 update. If the 915b is not approved, Summit will conduct additional background soil sampling to better understand the natural concentrations of inorganics in the soil at this site.

## SITE INVESTIGATION REPORT

### SAMPLE SUMMARY

**Soil**

Number of soil samples collected 5  
Number of soil samples exceeding 915-1 5  
Was the areal and vertical extent of soil contamination delineated? Yes  
Approximate areal extent (square feet) 350

**Groundwater**

Number of groundwater samples collected 0  
Was extent of groundwater contaminated delineated? No  
Depth to groundwater (below ground surface, in feet)           
Number of groundwater monitoring wells installed           
Number of groundwater samples exceeding 915-1         

**Surface Water**

0 Number of surface water samples collected  
         Number of surface water samples exceeding 915-1  
If surface water is impacted, other agency notification may be required.

**NA / ND**

ND Highest concentration of TPH (mg/kg)           
-- Highest concentration of SAR 15.1  
BTEX > 915-1 No  
Vertical Extent > 915-1 (in feet) 8

         Highest concentration of Benzene (µg/l)           
         Highest concentration of Toluene (µg/l)           
         Highest concentration of Ethylbenzene (µg/l)           
         Highest concentration of Xylene (µg/l)           
         Highest concentration of Methane (mg/l)         

**OTHER INVESTIGATION INFORMATION**

☐ Were impacts to adjacent property or offsite impacts identified?

☒ Were background samples collected as part of this site investigation?

One background sample was collected during Site excavation. Please see attached analytical data for details.

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)          Volume of liquid waste (barrels)         

☒ Is further site investigation required?

See Additional Investigative Actions

**REMEDIAL ACTION PLAN****SOURCE REMOVAL SUMMARY**

Describe how source is to be removed.

Site was excavated and sampled in August 2021.

**REMEDIATION SUMMARY**

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Summit intends to submit a 915b reclamation plan for the remainder of the exceedances at this Site with the next Form 27 update. If the 915b is not approved, Summit will conduct additional background soil sampling to better understand the natural concentrations of inorganics in the soil and produced water at this site.

**Soil Remediation Summary**

☐ In Situ

☐ Ex Situ

         Bioremediation ( or enhanced bioremediation )

         Excavate and offsite disposal

         Chemical oxidation

If Yes: Estimated Volume (Cubic Yards)         

         Air sparge / Soil vapor extraction

Name of Licensed Disposal Facility or COGCC Facility ID #

\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

\_\_\_\_\_ Excavate and onsite remediation  
\_\_\_\_\_ Land Treatment  
\_\_\_\_\_ Bioremediation (or enhanced bioremediation)  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Other \_\_\_\_\_

**Groundwater Remediation Summary**

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

**GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

## REMEDIATION PROGRESS UPDATE

### PERIODIC REPORTING

#### Approved Reporting Schedule:

☐ Quarterly☐ Semi-Annually☐ Annually☐ Other

#### ☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

#### Report Type:

☐ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☐ Other

### Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

The General coverage within the Arthur J. Gallagher Risk Management Services insurance program includes coverage for property damage, bodily injury to third parties, and sudden or accidental pollution that requires Remediation subject to a \$5,000,000 per occurrence. Grand River Gathering is in the process of obtaining a surety bond to provide Financial Assurance.

Operator anticipates the remaining cost for this project to be: \$ 5000

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? ☐

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

# RECLAMATION PLAN

## RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Summit intends to submit a 915b reclamation plan for the remainder of the exceedances at this Site with the next Form 27 update. If the 915b is not approved, Summit will conduct additional background soil sampling to better understand the natural concentrations of inorganics in the soil and produced water at this site.

Is the described reclamation complete? \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim ☐ Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

## SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. \_\_\_\_\_

Proposed date of completion of Reclamation. \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. \_\_\_\_\_

Actual Spill or Release date, or date of discovery. \_\_\_\_\_

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 08/03/2021

Proposed site investigation commencement. \_\_\_\_\_

Proposed completion of site investigation. 08/01/2023

### REMEDIAL ACTION DATES

Proposed start date of Remediation. \_\_\_\_\_

Proposed date of completion of Remediation. \_\_\_\_\_

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☐ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

**OPERATOR COMMENT**

This spill was excavated and sampled in August 2021. Results from the soil sampling event indicate exceedances in SAR, Arsenic, EC, and pH when compared to COGCC Residential Soil Screening Levels (RSSLS). All Arsenic exceedances reported were below the local background sample taken. Produced water was sampled and analyzed for Arsenic and pH from the nearby PN20 pad. The produced water sample indicates that the Arsenic and pH exceedances were likely naturally occurring. Please see the attached Operator Knowledge statement and soil analytical results for additional details.

Entrada recommends that Summit file an initial Form 27 Remediation Workplan with the COGCC. Once the Form 27 is approved, a request for closure should be filed for the initial spill/release report Form 19 (Document #402777584). Any future work will proceed under the Form 27.

Summit intends to submit a 915b reclamation plan for the remaining inorganic exceedances at this Site with the next Form 27 update. If the 915b is not approved, Summit will conduct additional background soil sampling to better understand the natural concentrations of inorganics in the soil at this site.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Sherri Gregg

Title: Env Compliance Specialist

Submit Date: 03/11/2023

Email: sherri.gregg@summitmidstream.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Steven Arauza

Date: 04/07/2023

Remediation Project Number: 28590

**COA Type****Description**

	Submit Supplemental eForm 19 to request closure of Spill/Release ID #480375. Supplemental report shall comply with outstanding COAs, indicate that work is proceeding under an approved eForm 27 and shall reference the Remediation Project number assigned upon approval of this report.
	Per Rule 913.b.(2), the Operator will conduct sampling and analysis of soil, and groundwater--if encountered, to determine the horizontal and vertical extent of any contamination in excess of the cleanup concentrations in Table 915-1 for soil and groundwater. The Operator shall analyze samples for the complete Table 915-1 list and shall compare analytical results for site investigation samples to the Table 915-1 Residential Soil Screening Level Concentrations. Submit an assessment of potential pathways to groundwater via a Supplemental Form 27.
2 COAs	

**Attachment Check List**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

<b><u>Att Doc Num</u></b>	<b><u>Name</u></b>
403337499	FORM 27-INITIAL-SUBMITTED
403338939	MAP
403338944	ANALYTICAL RESULTS
403338947	ANALYTICAL RESULTS
403338989	OTHER
403340258	ANALYTICAL RESULTS

Total Attach: 6 Files

**General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>
		Stamp Upon Approval

Total: 0 comment(s)