

# Inspection Photos

API: 071-09178

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/4/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09178 | Date: 4/4/2023

## Inspection Photos



**Photo 1.** Facing southwest at the beginning of the reclaimed access road. The perennial vegetation appears to be establishing along the reclaimed road.





## Inspection Photos



**Photo 2.** Facing southwest at the beginning of the reclaimed access road. The perennial vegetation appears to be establishing along the reclaimed road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09178 | Date: 4/42023



## Inspection Photos



**Photo 3.** Facing west towards the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09178 | Date: 4/42023



## Inspection Photos



**Photo 4.** Facing southwest down to the lower portion of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

API: 071-09178 | Date: 4/42023



## Inspection Photos



**Photo 5.** Facing northwest toward the upper portion of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09178 | Date: 4/42023



## Inspection Photos



**Photo 6.** There are some areas of erosion that should be repaired with BMP's to control further erosion.





## Inspection Photos



**Photo 7.** Facing down toward the bottom of the location. The berm at the bottom appears to need some maintenance due to erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09178 | Date: 4/42023



## Inspection Photos



**Photo 8.** Facing northeast at west side of the location. There are some areas of erosion that should be repaired with BMP's to control further erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09178 | Date: 4/42023



## Inspection Photos



**Photo 9.** Facing northwest toward the recontoured location. The perennial vegetation appears to be establishing but will need to be monitored to ensure vegetation fully establishes.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09178 | Date: 4/42023