

Inspection Photos

API: 071-07508

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/4/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07508 | Date: 4/4/2023

Inspection Photos



Photo 1. Facing southwest along the main access road. Areas of erosion along the road have been graded out.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07508 | Date: 4/4/2023

Inspection Photos



Photo 2. Facing south along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07508 | Date: 4/4/2023

Inspection Photos



Photo 3. Facing southeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07508 | Date: 4/4/2023