

# Inspection Photos

API: 071-09577

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/4/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09577 | Date: 4/4/2023

## Inspection Photos



**Photo 1.** Facing northwest along the access road. There are culverts filled in with sediment along the portion of the road sand stormwater is causing erosion of the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09577 | Date: 4/4/2023

## Inspection Photos



**Photo 2.** Facing northwest along the access road. There are culverts filled in with sediment along the portion of the road sand stormwater is causing erosion of the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09577 | Date: 4/4/2023

## Inspection Photos



**Photo 3.** Facing northeast toward the wellsite.

