

TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NWNE

Location # 335274



Wellheads – Photo #01937

Separators – Photo #01929

TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NWNE

Location # 335274



Tank Battery – Photo #01934



Open-Ended Line – Photo #01936

TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NWNE

Location # 335274



Erosion/Sediment Migrating Off Location – Photo #01931

Lack of Stabilization/Sediment Migration – Photo #01940

TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NWNE

Location # 335274



Degradation/Sediment Migration – Photo #01938

Degradation/Sediment Migration – Photo #01942