

# Inspection Photos

April 5, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 324015

Location Name: MACKLEY-66S94W/34SWSW

Inspection Document #: 702801430

Garfield County, CO

SWSW Section 34 T6S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: MACKLEY-66S94W/34SSW  
Location ID: 324015



**Photo 1.** Photo taken from the north shows an overview of the location.



Inspection Photos  
Location Name: MACKLEY-66S94W/34SWSW  
Location ID: 324015



Photo 2. Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801430



Inspection Photos  
Location Name: MACKLEY-66S94W/34SWSW  
Location ID: 324015



**Photo 3.** Photos show lack of stabilization of the pad surface.



Inspection Photos  
Location Name: MACKLEY-66S94W/34SWSW  
Location ID: 324015



**Photo 4.** Photos show unmarked anchors to the southwest (left) and north (right).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801430



Inspection Photos  
Location Name: MACKLEY-66S94W/34SWSW  
Location ID: 324015



**Photo 5.** Photos show interim areas.