

Inspection Photos

April 5, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 323991

Location Name: WPX Energy/RMV 108-4

Inspection Document #: 702801432

Garfield County, CO

Lot 2 Section 4 T7S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WPX Energy/RMV 108-4
Location ID: 323991



Photo 1. Photo taken from the west shows an overview of the location.



Inspection Photos
Location Name: WPX Energy/RMV 108-4
Location ID: 323991




Photo 2. Photos show production areas.



Inspection Photos
Location Name: WPX Energy/RMV 108-4
Location ID: 323991



Photo 3. Photos show production areas.



Inspection Photos
Location Name: WPX Energy/RMV 108-4
Location ID: 323991



Photo 4. Photo shows bull plugs not installed on tank drain lines.



Inspection Photos
Location Name: WPX Energy/RMV 108-4
Location ID: 323991




Photo 5. Photo shows bull plugs not installed on tank drain lines from previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801432

Inspection Photos
Location Name: WPX Energy/RMV 108-4
Location ID: 323991



Photo 6. Photo shows an unmarked anchor to the south of the wells.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801432

Inspection Photos
Location Name: WPX Energy/RMV 108-4
Location ID: 323991



Photo 7. Photos show lack of stabilization/compaction from previous inspection (left) and current inspection (right).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801432

Inspection Photos
Location Name: WPX Energy/RMV 108-4
Location ID: 323991



Photo 8. Photos show lack of stabilization/compaction from previous inspection (left) and current inspection (right).

Inspection Photos
Location Name: WPX Energy/RMV 108-4
Location ID: 323991



Photo 9. Photos show slopes at the south of the location are snow covered.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801432

Inspection Photos
Location Name: WPX Energy/RMV 108-4
Location ID: 323991



Photo 10. Photos show interim areas.