

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo 1 WH sign has old operator information.

Photo 2 Dead weeds around the WH.

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo 3 Pump jack.



Photo 4 Gas engine.

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo 5 Stained soil by the Pump Jack gas engine.




Photo 6 Stained soil by the Pump Jack gas engine.

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo 7 Trash in PJ base.

Photo 8 TB sign has old operator information.

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo 9 TB.

Photo 10 Dead weeds in TB berm.

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo 11 Stained soil under plug on crude oil tank .



Photo 12 Stained soil under valve on crude oil tank .

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo 13 Stained soil under valve on crude oil tank .



Photo 14 produced water tank.

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo 15 Gas Meter Run.



Photo 16 Vertical Heated Separator.

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo 17 ECD.