

Stormwater Inspection

February 10, 2023

Operator: CCRP OPERATING INC - #10665

Location ID: 421908

Inspection Document #: 697504593

Weld County, CO

SESW Section 11 T11N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources_s

Inspection Photos

Location Name: Wagner #11-65 11-1H

Location ID: 421908




Photo 1. Photo illustrates a portion of the access road crosses a High Priority Habitat (Aquatic Native Species Conservation Waters) at Gearly Creek. Operator has failed to prevent sediment discharge into Gearly Creek- refer to the photos 2.

Note- this is a shared access road with Upland Exploration.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697504593

Inspection Photos

Location Name: Wagner #11-65 11-1H

Location ID: 421908



Photo 2. Photo taken from intersection of the access road and Geary Creek, facing South. Photo illustrates sediment discharge into Geary Creek without stormwater BMPs.



Photo 3. Photo taken from Geary Creek, facing North. See comments under Photo 2.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Number: 697504593

Inspection Photos

Location Name: Wagner #11-65 11-1H

Location ID: 421908



Photo 4. Photo taken from Geary Creek, facing South. Photo illustrates sediment discharge into Geary Creek.

