

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 203-20 Pad

Location ID: 323961



Photo # 4844 Access road to location



Photo # 4672 From Inspection 708900240 conducted on 04/07/2023

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 203-20 Pad

Location ID: 323961



Photo # 4725 Access road to location



Photo # 4674 From Inspection 708900240 conducted on
04/07/2023

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 203-20 Pad

Location ID: 323961



Photo # 4730 Access road to location



Photo # 4676 From Inspection 708900240 conducted on
04/07/2023

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 203-20 Pad

Location ID: 323961



Apr 10, 2023 at 10:20:06 AM
CO



Apr 7, 2023 at 11:38:10 AM
CO

Photo # 4726 Access road to location

**Photo # 4678 From Inspection 708900240 conducted on
04/07/2023**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 203-20 Pad

Location ID: 323961



Photo # 4804 Access road to location



Photo # 4681 From Inspection 708900240 conducted on
04/07/2023

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 203-20 Pad

Location ID: 323961



Photo # 4817 Access road to location



**Photo # 4683 From Inspection 708900240 conducted on
04/07/2023**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 203-20 Pad

Location ID: 323961



Photo # 4738 Access road to location



**Photo # 4685 From Inspection 708900240 conducted on
04/07/2023**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 203-20 Pad

Location ID: 323961



Photo # 4750 Access road to location



**Photo # 4687 From Inspection 708900240 conducted on
04/07/2023**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 203-20 Pad

Location ID: 323961



Photo # 4737 Access road to location



Photo # 4689 From Inspection 708900240 conducted on
04/07/2023

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 203-20 Pad

Location ID: 323961



Photo # 4770 Access road to location



Photo # 4690 From Inspection 708900240 conducted on
04/07/2023

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 203-20 Pad

Location ID: 323961



Photo # 4731 Access road to location



Photo # 4693 From Inspection 708900240 conducted on
04/07/2023

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 203-20 Pad

Location ID: 323961



Photo # 4727 Access road to location



Photo # 4695 From Inspection 708900240 conducted on
04/07/2023

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 203-20 Pad

Location ID: 323961



Photo # 4753 Multi Chem truck driving through creek & washed out access road.



Photo # 4756 Multi Chem truck driving through creek & washed out access road.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 203-20 Pad

Location ID: 323961



Photo # 4757 Multi Chem truck driving through creek & washed out access road.



Photo # 4758 Multi Chem truck driving through creek & washed out access road.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 203-20 Pad

Location ID: 323961



Apr 10, 2023 at 10:32:26 AM
CO



Apr 10, 2023 at 10:35:00 AM

Photo # 4759 Multi Chem truck driving through creek & washed out access road.

Photo # 4764 Access road