

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 218-21 Pad

Location ID: 335341



Apr 10, 2023 at 11:28:16 AM  
CO



Apr 10, 2023 at 11:29:21 AM  
CO

Photo # 4882 From entrance to location

Photo # 4883 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 218-21 Pad

Location ID: 335341



Photo # 4885 Stained soils & gravel



Photo # 4886 Stained soils & gravel





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 218-21 Pad

Location ID: 335341



Photo # 4875 Access road



Photo # 4877 Access road



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 218-21 Pad

Location ID: 335341



Apr 10, 2023 at 11:27:27 AM  
CO

Photo # 4880 Access road



Apr 10, 2023 at 11:36:30 AM  
CO

Photo # 4910 Access road