


CAERUS PICEANCE LLC, GASAWAY FED-66S99W/26NWSW

Location # 323867



Location – Photo #02008

Wellhead – Photo #02009

CAERUS PICEANCE LLC, GASAWAY FED-66S99W/26NWSW

Location # 323867



Separator – Photo #02013



Tank Battery – Photo #02010

CAERUS PICEANCE LLC, GASAWAY FED-66S99W/26NWSW

Location # 323867



Debris – Photo #02012



Lack of Secondary Containment – Photo #02014

CAERUS PICEANCE LLC, GASAWAY FED-66S99W/26NWSW

Location # 323867



Lease Road Erosion – Photo #02005



Inadequate Tracking BMP – Photo #02015