

CAERUS PICEANCE LLC, GASAWAY (FERDERAL)-66S99W/27NENE

Location # 323864




Location – Photo #02017



Wellhead – Photo #02019

CAERUS PICEANCE LLC, GASAWAY (FERDERAL)-66S99W/27NENE

Location # 323864



Separator – Photo #02018



Tank Battery – Photo #02021



CAERUS PICEANCE LLC, GASAWAY (FERDERAL)-66S99W/27NENE

Location # 323864



Unused Equipment – Photo #02024



Erosion Channel/Transport of Sediment – Photo #02025

CAERUS PICEANCE LLC, GASAWAY (FERDERAL)-66S99W/27NENE

Location # 323864



Site Degradation Due to Snow Plow – Photo #02026



Degradation/Transport of Sediment – Photo #02027