

BW Musser 1
 API 05-081-05453
 Docket No. 210400055
 Semi-Annual LDAR Testing

TARGET ONLINE Company List Change Password Contact Us Log out

Emission Repair Track Assessment Map View Reports Repair Management

Assessment List and Summary EMISSION DETAIL REPORT EXPORT TO EXCEL Facility: BW MUSSER 1 WELLHEAD ; Assessment Date: 02/09/2023 (Filtered 0 records/Total 0 records) CLEAR ALL FILTERS

Summary

Dominion
 Facility Name: BW MUSSER 1 WELLHEAD
 Facility Location: 40-946396 / -106-311453
 Assessment Date: 02/09/2023
 Assessment ID: 3061675973150
 Assessment Type(s): CO Reg 7
 Technician(s): G Allen
 Start Date: 2023-02-09 13:31:00.0
 End Date: 2023-02-09 13:05:00.0
 Instruments: Dominion 620GF OGI-1

Emissions Summary	Total	Repaired
Leaks:	0	0
Mandatory Leaks:	0	0
Vents:		
Repair Required	0	0
No Repair Required	0	-
Mandatory No Emissions:	0	-

Comments:
No emissions detected

Filtered Assessment List

All	Emission ID	Emission Type	Description	Safety Concern	Flow Rate (ft ³ /min)	Emission Severity	LDAR Tag #	PPM	Gas \$ /Year	Picture	Video	First Attempt Due Date	Final Repair Due Date	Repair Status
No emissions detected														

Semi-annual testing was conducted on 2/9/23 and no leaks were identified.