

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /3NWNW

Location ID: 334598



Photo #9570 From entrance to location.



Photo #9571 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /3NWNW

Location ID: 334598



Photo #9593 Calibration cards not conspicuously posted.